

## Melt Pressure Indicator / Alarms



### [MP9410 MELT PRESSURE INDICATOR](#)

- \* 350ohm Strain Gauge Input
- \* Scaleable Range
- \* 2 Configurable Alarms HIGH/LOW/OFF
- \* AUTO/MANUAL Calibration
- \* Manual ZERO
- \* Lockout
- \* Process Value - RETRANS

### [MP9610 MELT PRESSURE INDICATOR](#)

- \* 350ohm Strain Gauge Input
- \* Scaleable Range
- \* 2 Configurable Alarms HIGH/LOW/OFF
- \* AUTO/MANUAL Calibration
- \* Manual ZERO
- \* Lockout
- \* Process Value - RETRANS

### [MPT9610 DUAL PRESSURE & TEMP](#)

- Same as \*MP9410,MP9610 plus:
- \*T/C J Temp input
  - \*3 Alarms

### [MG-IND DIGITAL PRESSURE METER](#)

- \* Can Attach to any Strain Gauge Transducer
- \* Large 5-DIGIT DIGITAL Display (0.8")
- \* LED Bar Graphs (Process & Set Value)
- \* PV Retransmission (4-20mA)
- \* Manual ZERO

### [MPC9610 - MELT PRESSURE CONTROL](#)

- \* Manual PID Tuning
- \* Fast Sampling Rate - 100mS
- \* Control Response Time - 100mS
- \* PV Retransmission (4-20mA)
- \* AUTO/MANUAL Calibration

### Melt Pressure Kits



### Transducer Repairs

